

## Physical Maintenance of the PC.

To maintain Your Machine in good working order, clean and dust the sucker every once and a while.

### Tools:

Dust Rag and a bottle of glass cleaner.  
A can of liquid Air and a screw driver.  
A bottle of Rubbing Alcohol.  
A box of "Q" tips.

### Key board:

Turn the keyboard upside down and shake out all the bread and cookie grums. Then take the air can and blow it out.

### Mouse and Mousepad:

Wash the mousepad with soap and water and let it dry after rinsing.

Turn the mouse upside down and unscrew the Ballcover, take the ball out.

Now take a Qtip, wet it with rubbing alcohol and take off the scum buildup on the 2 shafts and 1 roller.

Wipe the Ball off, and reassemble.

### Monitor:

Use the rag only and dust the whole thing.

Spray Glass cleaner on the Rag only! Not on the screen direct.

And clean the scum off the screen and Monitor case.

### Tower:

Open the case and blow it out with the can of Air.

Wipe the tower with a glass cleaner damp cloth and dry.